

Figure 43
Hydrogeologic Cross Section E - E'

October 2003

TODD ENGINEERS
Emeryville, California