



Aerial photo of Henry Tosta Dairy's production area. Note the large amount of manure to the right of all the structures on property. Excessive manure has been accumulating on site for at least the last five years.



Photo taken from the northeast corner of the production area looking to the southwest; note lack of distinction between manure storage areas. Excessive manure has been allowed to accumulate.



Photo of uncontrolled wastewater creeping into a corral at the Henry Tosta Dairy.



Photo of cows at the Henry Tosta Dairy standing in wastewater and manure slurry that has backflowed from the wastewater pond located to the right of the corral fence.



Photo of puddles of wastewater remaining on the lagoon embankments adjacent to the solids settling basin; puddles of wastewater demonstrate the embankments of the solids settling basin had recently over-topped.



Photo of solids settling basin #2. Note excessive accumulated manure and wastewater contained in the basin; no freeboard was observed.