Mon file: Los Osos CSD WMP

05 JUN 23 PM 1:58

895 ASHLAND ST., STE. 101
SAN LUIS OBISPO, CA 93401

LOS OSOS
NITRATE MONITORING PROGRAM

APRIL 2005
GROUND WATER MONITORING

Prepared for the

LOS OSOS COMMUNITY SERVICES DISTRICT



June 2005

RECEIVED
JUN 21 2005
BY:

CLEATH & ASSOCIATES
1390 Oceanaire Drive
San Luis Obispo, California 93405

(805) 543-1413


Base map: USGS Topo, Morro Bay South
Map Scale: 1 inch = 1,000 feet
Network monitoring location
Ground water elevation contour in feet above mean sea level
Inferred direction of ground water flow
18.9 ground water elevation in feet above mean sea level
N
1000 feet
Figure 1
Ground Water Elevations
LOCSD Monitoring Network
April 2005
Los Osos CSD
Cleath & Associates
11.8
42.9
43.6
63.9
22.6
20.2
65.5
18.9
13.3
26.2
34.7
88.4
13.4
107.7
53.0
18.2
53.5
38.9
160.5
142.1
EAST SIDE
WEST SIDE
Elfin forest
Baywood Park
Cuesta-by-the-Sea
Golf Course
Mud
Sunnys
Mobile Home Park
Water Tank
Seeps
7K3
7L3
7G1
7R1
7N1
8N2
17D
18C1
18B1
18A
13A
18E1
13G
13H
13L5
13Q1
18L3
18L5
18J6
18N1
18H3
17F4
17N4
18R1
20B
24A


Base map: USGS Topo, Morro Bay South
Map Scale: 1 inch = 1,000 feet
Network monitoring location
[10] Inferred NO_3-N concentration contour (mg/l)
10 NO_3-N concentration (mg/l)
N
1000 feet
Figure 2
NO_3-N Concentrations (mg/l)
LOCSD Monitoring Network
April 2005
Los Osos CSD
Cleath & Associates
Morro Bay
Elfin forest
Dance
Baywood Park
Cuesta-by-the-Sea
EAST SIDE
WEST SIDE
South Bay Community
Sunnyside Sch
Golf Course
Water Tank
Mobile Home Park
Mud
19
14
12
2.2
18
10
20
<0.5
[5]
[10]
[15]
[20]
2.4
14
0.5
7.9
8.9
1.3
9.6
28
13
4.4
21
12
15
5.1
11
2.5


Base map: USGS Topo, Morro Bay South
Map Scale: 1 inch = 1,000 feet
Network monitoring location
[3001] Inferred TDS concentration contour (mg/l)
340 Total Dissolved Solids concentration (mg/l)
N
1000 feet
Figure 3
TDS Concentrations (mg/l)
LOCSD Monitoring Network
April 2005
Los Osos CSD
Cleath & Associates
490
410
260
67
120
340
280
110
330
270
130
240
EAST SIDE
330
1100
210
360
330
470
WEST SIDE
370
220
390
200
340
Elfin forest
Dance
Mud
Cuesta-by-the-Sea
Golf Course
South Bay Community Park
Sunnyside Sch
Mobile Home Park
Water Tank
7L3
7K
7Q1
7R1
8N2
18C1
17D
18BD
18A
13A7
18E1
13G
13H
13L5
13Q1
18H3
17E4
18L4
18L3
18J6
18N1
18R1
17N4
20B
13AV
24A