

CENTRAL VALLEY REGIONAL WATER QUALITY CONTROL BOARD

INSPECTION REPORT

DISCHARGER: Clark Pacific Precast

LOCATION & COUNTY: 40600 County Road 18C, Woodland. Yolo County

CONTACT(S): Ryan Nakken, Plant Engineer

INSPECTION DATE: 11 July 2012

INSPECTED BY: Brendan Kenny, Engineering Geologist

ACCOMPANIED BY: Greg Waters, Student Assistant

OBSERVATIONS AND COMMENTS: No PCC was being removed from the site at the time of inspection. Crews were working along the east side of "Area A" to remove vegetation and determine the depth to native soil. A water truck was actively watering the area where an excavator and grader were working. Occasional dust clouds were observed from active work areas and entrance/exit roads but the dust did not appear to leave the property boundary, except for one dust cloud generated by the water truck operating in "Area A". Water applied for dust control purposes was observed throughout most of the area that was inspected, including the entrance/exit road. Track out marks on County Road 100B were observed where trucks exit the PCC pile area. Rocks placed on the PCC pile entrance road to reduce track out appeared to have settled and compacted, reducing their effectiveness. No tracking marks were visible on County Road 18C or Best Ranch Road. A photographic inspection log is attached.

SUMMARY: Area seemed to be well maintained. BMPs to reduce track out should be re-evaluated and implemented to reduce track out on county roads.

-Original Signed By-
BRENDAN KENNY

Approved:		
-----------	--	--



Entrance to PCC pile area. Note track out on road and wet area from water applied for dust control.



Entrance Road to PCC Pile area. Vegetation on undisturbed area. Tractor on current work/removal area.



Crust that forms on PCC piles after applying water.



Road cut showing undisturbed PCC on top of soil.



Vegetation being removed from "Area A."



Water truck applying water to east berm of "Area A." for dust control.



Water being applied to active work area for dust control.



East berm and property line of "Area A."



PCC pile area. Grader in front for scale.



North side of PCC pile area. White line at the base of the pile is the top of a water truck leaving the area to re-fill.



Water truck leaving the site to be refilled.

